

# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image1**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Front overview



**Image2**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Left overview



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image3**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Back overview



**Image4**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Wind blown tree damaged the back left slopes



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image5**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Gutter damage



**Image6**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Retaining wall damage



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image7**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Retaining wall damage



**Image8**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Deck damage on the right side of the house



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image9**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Deck damage



**Image10**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Tree weight caused the deck to tilt out of level



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image12**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Roof overview



**Image13**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Roof overview



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image15**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Roof puncture in the left slope



**Image16**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Roof puncture in the left slope



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image17**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Roof puncture in the left slope



**Image18**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Tree limbs against the chimney



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image19**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

W valley metal



**Image21**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

End flashing damaged



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image22**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Shingle damage on the left slope



**Image23**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Shingle damage to the left slope



# Photo Sheet

National Catastrophe Team

P.O. Box 672041  
Dallas, Texas 75267  
Phone: (800) 547-8676  
Fax: (888) 859-3946

Insured: ALEKSEY RUKAVISHNIKOV

Claim #: 0537010878

Policy #: 000987175711



**Image24**

Date Taken: 3/16/2019

Taken By: Benjamin Danosky

Back slope roof puncture